

Technical Bulletin

Model 928 S4, 944S	Group 0
Part Identifier 0300	Number 8901

Subject: Performing System Adaption If Battery was Disconnected

Vehicles from Model Year 1988 with self diagnosis capability.

Each time the battery or the DME/LH control unit plugs are disconnected, system adaption **must** be performed. This is done after reconnecting the battery or the DME/LH control units. If adaption is not performed, the engine idle RPM could drop too low and cause the engine to stall with closed throttle.

For system adaption procedures refer to 944 or 928 Workshop Manual, Volume 1, page 03-15.

PORSCHE CARS NORTH AMERICA, INC.

Important Notice

PCNA Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers.

© 1989 Porsche Cars North America, Inc.

013325



SERVICE

Page 1 of 1
January 13, 1989