

# Technical Bulletin

Model

All

Group

2

**Subject:** Spark Plug Thread Lubrication

Part Identifier

2870


Number

9102

**ATTENTION: Service Manager/Service Technician**

**This bulletin supersedes Technical Bulletin Group 28, Number 78-03, Book A, page 297.**

**Models Affected:** All



**Concern:**

Spark plug thread lubrication.

**Service Information:**

The Carrera 2/4 Workshop Manual Vol. 1, page 03-11, in the section on replacing spark plugs states "Do not use any lubricant on the (spark) plug threads."

This procedure now applies retroactively to all Porsche models. All spark plugs should be installed with the threads clean and dry.

The torque specification is unchanged: 25-30 Nm (19-22 ft. lb.).

.....  
Index # 027657  
.....

2

PORSCHE CARS NORTH AMERICA, INC.

